[Notes] C Compiler Package for RL78 Family (CCRL#028)

R20TS0714EJ0100 Rev.1.00 Jul. 01, 2021

Overview

When using the CC-RL C compiler package for the RL78 family, note the following point:

- 1. When an invalid bit position is specified for a bit-manipulation instruction (CCRL#028) Note: The number following the note is an identification number for the precaution.
- 1. When an invalid bit position is specified for a bit-manipulation instruction (CCRL#028)

1.1 Applicable Products

CC-RL V1.01.00~V1.10.00

1.2 Details

Specifying an invalid value (a value other than 0 to 7) to a bit position for a bit-manipulation instruction on an assembly source program is supposed to cause an error in assembly, but an object might be created without causing an error. Note that this does not apply to assembly instructions generated by the compiler. However, this applies to assembly instructions (that meet the conditions) described in the #pragma inline_asm function.

1.3 Conditions

This note applies to assembly statements that meet all the conditions from (1) to (3):

- (1) One of the following bit-manipulation instructions is described: mov1, and1, or1, xor1, set1, clr1, bt, bf, btclr, .bt, and .bf
- (2) An operand is specified in either of the following formats: [HL].bit ES:[HL].bit
- (3) A value other than 0 to 7 is specified for a bit position in (2).

1.4 Examples

Examples of the problem are shown below. The parts corresponding to the conditions are shown in red.

[Example 1]

asrl -cpu=S3 tp1.asm

```
# tp1.asm
bt [hl].-1,$L1 ; (1) (2) (3)
```

In this example, an object is created as the following instruction.

```
bt a.7,$L1
```

[Example 2]

asrl -cpu=S3 tp2.asm

```
# tp2.asm
set1 [hl].-1 ; (1) (2) (3)
sub x,a
```

In this example, the following instruction sequences are created. As shown in this example, an object different from the original source program might also be generated in subsequent instructions.

```
set1 0xffe71.7
subw sp,#0
```



1.5 Workaround

Use an integer from 0 to 7 when specifying a bit position for a bit-manipulation instruction.

1.6 Schedule for fixing the problem

The problem will be fixed in CC-RL V1.11.00. The release date has not yet been decided.

Revision History

		Description	
Rev.	Date	Page	Summary
1.00	Jul.01.21	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061, Japan www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit: www.renesas.com/contact/.

© 2021 Renesas Electronics Corporation. All rights reserved.

TS Colophon 4.2