

[Upgrade to revision]

R20TS0631EJ0100

Rev.1.00

Oct. 16, 2020

CS+ Code Generator for RL78 (CS+ for CC) V2.20.00,

CS+ Code Generator for RL78 (CS+ for CA,CX) V2.20.00,

e² studio Code Generator Plug-in V2.16.0

Outline

The products in the title will be revised and their version numbers will be changed as follows:

- (1) CS+ Code Generator for RL78 (CS+ for CC): V2.19.00 to V2.20.00
- (2) CS+ Code Generator for RL78 (CS+ for CA, CX): V2.19.00 to V2.20.00
- (3) e² studio Code Generator plug-in: V2.15.0 to V2.16.0

1. Version to Be Updated

- All revisions up to V2.19.00 of CS+ Code Generator for RL78 (CS+ for CC)
- All revisions up to V2.19.00 of CS+ Code Generator for RL78 (CS+ for CA,CX)
- All revisions up to 2020- 07 of e² studio (V2.15.0 of Code Generator plug-in)

2. Items Revised

The major revision points are as follows: Refer to the following release note for details.

- Code Generator for RL78
CS+ Code Generator for RL78 (CS+ for CC/CA,CX) V2.20.00,
e² studio Code Generator Plug-in, V2.16.0,
AP4 for RL78 V1.19.00, Applilet3 for RL78 V1.19.00 Release Note. This information will be released on October 20.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut4632>

2.1 Description of Modification

The problems regarding the points below have been fixed.

(1) RENESAS TOOL NEWS, Document No. R20TS0544EJ0100

1. When using the trace function of the on-chip debug setting

Applicable devices: The following devices of the RL78/F15 group(*):

R5F113PG, R5F113TG, R5F113PH, R5F113TH, R5F113PJ, R5F113TJ,
R5F113GK, R5F113LK, R5F113MK, R5F113PK, R5F113TK

(*): Except for R5F113mL (m = G, L, M, P, and T)

For details about the problems, refer to the following URL:

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0544>

(2) RENESAS TOOL NEWS, Document No. R20TS0545EJ0100

1. Callback function setting of CSI and UART

Applicable devices: RL78/I1E and RL78/G11(*1) groups

(*1): R5F1054A(16pin), R5F1056A(20pin), R5F1057A(24pin), R5F1058A(25pin)

2. Operation that cancels pin function assignment of CSI and UART

Applicable devices: RL78/I1E group

For details about the problems, refer to the following URL:

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0545>

3. How to Update Your Copy

Online updating is available free of charge. The method of updating depends on the version of your IDE.

3.1 For CS+ V3.00.00 or Later

To update your program, use either of the following methods:

- (1) From the Windows Start menu, select Renesas Electronics CS+ to start the Update Manager and update the program. This service will be available from October 20.

Note: If your CS+ has been launched with rapid startup enabled, exit the CS+ once, and then run the Update Manager.

If the CS+ is resident in the notification area of Windows (system tray) due to rapid startup, an error occurs and produces the following message:

M0120001

"CubeSuiteW+.exe"

Installation is suspended because "CubeSuiteW+.exe" is running.

It will be resumed next time you start the tool.

- (2) Download and install the desired software tools from the following URL.
(The file will be available from October 20.)

https://www.renesas.com/cs+_download

3.2 For CubeSuite+ V2.00.00 to 2.02.00

Update your file in the same way as described in section 3.1 above.

(Substitute the term "Renesas Electronics CS+" with "Renesas Electronics CubeSuite+".)

3.3 For CubeSuite+ V1.03.00 or Earlier

The Update Manager is not supported in CubeSuite+ V1.03.00 or earlier.

Download the evaluation edition of CS+ for CC V8.04.00 or CS+ CA, CX V4.04.00 from the following URL and then update your file.

https://www.renesas.com/cs+_download

3.4 For e² studio

For the method of updating e² studio, refer to section 3, "Updating Your Product" in RENESAS TOOL NEWS, Document No. R20TS0605EJ0100.

<https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ts0605>

You cannot update Code Generator plug-in by itself.

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Oct.16.20	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URL in the Tool News also may be subject to change or become invalid without prior notice.

Corporate Headquarters

TOYOSU FORESIA, 3- 2- 24 Toyosu,
Koto-ku, Tokyo 135- 0061, Japan

www.renesas.com

Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

Contact information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:

www.renesas.com/contact/