

---

[Upgrade to Revision]

R20TS1011EJ0100

Rev.1.00

CS+ Device Information for RH850 V8.11.01

Apr. 16, 2024

---

## Outline

CS+ Device Information for RH850 family has been revised from V8.11.00 to V8.11.01.

### 1. Version to Be Updated

- CS+ Device Information for RH850 V3.00.00 or later
- CubeSuite+ Device Information for RH850 (CubeSuite+ DevInfo\_RH850) V1.00.04 or earlier

To check the version of "CS+ Device Information for RH850" or "CubeSuite+ DevInfo\_RH850", follow the instructions under "Components" at the URL below.

<https://www.renesas.com/cs+ ver>

### 2. Items Revised

The major revision points are as follows: For details, see the following URL.

(The information will be available from April 22.)

[https://www.renesas.com/cs+/eng/CSPlus\\_DevInfo\\_RH850.html](https://www.renesas.com/cs+/eng/CSPlus_DevInfo_RH850.html)

#### 2.1 Correction of Device Information

Part of device information for the following MCU groups has been corrected.

- RH850/U2A group
- RH850/U2B group

### 3. Updating Your Product

#### 3.1 CS+ V3.00.00 or Later

Update in either of the following ways.

- (1) From the Windows Start menu, select Renesas Electronics CS+, and then run Update Manager to update your file. (This service will be available from April 22.)

Note: If your CS+ has been launched with rapid startup enabled, exit the CS+ once, and then run the Update Manager.

If the CS+ is resident in the notification area of Windows (system tray) due to rapid startup, an error occurs and produces the following message:

---

M0120001

"CubeSuiteW+.exe"

Installation is suspended because "CubeSuiteW+.exe" is running.

It will be resumed next time you start the tool.

---

- (2) Download and install the desired software tools from the following URL

(The file will be available from April 22.)

<https://www.renesas.com/us/en/software-tool/cs#download>

### 3.2 CubeSuite+ V2.00.00 to V2.02.00

Update your file in the same way as described in section 3.1.

### 3.3 CubeSuite+ V2.02.00 or Earlier

The Update Manager is not supported in CubeSuite+ V2.02.00 or earlier. You will need to install the evaluation edition of the Update Manager. Download the evaluation edition of CS+ for CC V8.11.00 from the following URL.

Then, update your file in the same way as described in section 3.1.

<https://www.renesas.com/us/en/software-tool/cs#download>

**Revision History**

Rev.	Date	Description	
		Page	Summary
1.00	Apr.16.24	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

**Corporate Headquarters**

TOYOSU FORESIA, 3-2-24 Toyosu,  
Koto-ku, Tokyo 135-0061, Japan  
[www.renesas.com](http://www.renesas.com)

**Trademarks**

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

**Contact information**

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:  
[www.renesas.com/contact/](http://www.renesas.com/contact/)