

RENESAS TOOL NEWS on April 1, 2004: RSO-HEW_3-040401D

A Note on Using E7 Emulator Software

Please take note of the following problem in using the E7 Emulator Software:

- On opening source files using the Editor window of the High-performance Embedded Workshop
-

1. Versions Concerned

The E7 emulator software V.2.0.01, V.2.0.02 and V.2.1.00

2. Description

When a target program developed for any of the R8C/Tiny series MCUs is debugged using a product concerned, the High-performance Embedded Workshop may display incorrect addresses in the Source Address column at the left of its Editor window or terminate unsuccessfully.

3. Condition

This problem occurs if a source file with line information is linked after another source file without that(*) and then the latter is opened in the Editor window.

NOTE:

- * For instance, a source file in which only the inclusion of header files is described.

4. Workaround

This problem can be circumvented in either of the following ways:

- (1) Add a dummy source code to the source file without line information.
- (2) Link the source file without line information after any of those with line information.

5. Schedule of Fixing the Problem

We plan to fix this problem in our next release of the product (the E7 emulator software V.3.2.00).

[Disclaimer]

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included. The URLs in the Tool News also may be subject to change or become invalid without prior notice.

© 2010-2016 Renesas Electronics Corporation. All rights reserved.