

# [Upgrade to Revision] Smart Configurator for RH850 V1.9.0

R20TS0959EJ0100  
Rev.1.00  
Jul. 16, 2023

## Outline

The product in the title has been updated as follows.

- (1) Smart Configurator for RH850: From V1.8.0 to V1.9.0

## 1. Products to Be Updated

- Smart Configurator for RH850 V1.8.0. and earlier

## 2. Description

A main change is as follows. For details, refer to the Release Note at the URL below.

<https://www.renesas.com/software-tool/rh850-smart-configurator#documents>

Smart Configurator for RH850 V1.9.0 Release Note (the note will be uploaded on July 20)

### 2.1 Fixed the issue that the Interrupt generation function does not work in Error Control Module

When "Interrupt generation" is selected in Error Control Module, the setting code for register "ECMINCFGi\_j" is not generated in driver code.

This issue is fixed from Smart Configurator for RH850 V1.9.0

For other fixes, please refer to the release notes above.

### 3. Updating the Product

Update in either of the following ways.

- (1) Download the latest Smart Configurator for RH850 from the URL below and install it (V1.9.0 will be released on July 20).

<https://www.renesas.com/rh850-smart-configurator#downloads>

Smart Configurator for RH850 V1.9.0

- (2) On the Windows Start menu, select Programs, Renesas Electronics CS+, and then run the Update Manager (this service will be available from July 20).

**Note: If you have started CS+ with the Rapid Startup function enabled, exit CS+, and then start the Update Manager.**

**If the Rapid Startup function is enabled and the CS+ icon is shown in the Windows notification area, the following error occurs.**

---

M0120001

"CubeSuiteW+.exe"

Installation is suspended because "CubeSuiteW+.exe" is running.

It will be resumed next time you start the tool.

## Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Jul.16.23	-	First edition issued

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

## Corporate Headquarters

TOYOSU FORESIA, 3-2-24 Toyosu,  
Koto-ku, Tokyo 135-0061, Japan  
[www.renesas.com](http://www.renesas.com)

## Trademarks

Renesas and the Renesas logo are trademarks of Renesas Electronics Corporation. All trademarks and registered trademarks are the property of their respective owners.

## Contact Information

For further information on a product, technology, the most up-to-date version of a document, or your nearest sales office, please visit:  
[www.renesas.com/contact/](http://www.renesas.com/contact/)