

PCN#: [EPMP-IMB-24-0011-1]

PC-MCU-A024A/E

# **Product Change Notice (PCN)**

Subject: Notice of Change in Materials for SH7615 Group and SH7616 Group LQFP Products

Publication Date: 2/16/2024

Effective Date: 12/1/2024

Revision History: Initial release

## Description of Change:

Affected Products: SH7615 Group and SH7616 Group LQFP Products Assembly Site: Renesas Electronics Co., Ltd Yonezawa Factory Changes: Die-bonding materials will be changed to a material

that is used in mass production for other Renesas's Products.

#### **Affected Product List:**

NO.	Booking Part Number	Package	Number of Pins
1	HD6417615ARFV	LQFP	208
2	HD6417616SFV	LQFP	208

#### Reason for Change:

Due to EOL of material by vendor, the materials will be changed to alternative material.

## Impact on Fit, Form, Function, Quality & Reliability:

This change will not affect fit, form, function, quality, and reliability.

## **Product Identification:**

Our production history data can be queried by using the trace code of the product.

Qualification Status: Reliability data is available.

Sample Availability Date: Not applicable

Device Material Declaration: Please contact our sales representatives or distributors.

PCN#: [EPMP-IMB-24-0011-1] PC-MCU-A024A/E

### Note:

- 1. Acknowledgement must be received by Renesas within 30 days or Renesas will consider the change as approved.
- 2. If timely acknowledgement is provided by Customer, then Customer shall have 90 days from the date of receipt of this PCN to make any objections to this PCN. If Customer fails to make objections to this PCN within 90 days of the receipt of the PCN then Renesas will consider the PCN changes as approved.
- 3. If customer cannot accept the PCN then customer must provide Renesas with a last time buy demand and purchase order.

For additional information regarding this notice, please contact your Renesas sales representative.