[Upgrade to revision] e² studio Code Generator Plug-in, AP4 Coding Assistance Tool for RZ

R20TS0255EJ0101 Rev.1.01 Jan. 16, 2018

Outline

The products in the title will be revised and their version numbers will be changed as follows.

- (1) e² studio Code Generator Plug-in: V2.9.0 to V2.10.0
- (2) AP4 Coding Assistance Tool for RZ: V1.06.00 to V1.07.00

1. Products and Versions to Be Updated

- All revisions up to V6.1.0 of e² studio (V2.9.0 of the Code Generator plug-in)
- ➤ All revisions up to V1.06.00 of the AP4 coding assistance tool for RZ

2. Items Revised

See 2.1 for the major revision points. For details, refer to the following Release Notes.

- ➤ e² studio Code Generator Plug-in
 - e² studio V6.2.0 Release Note (This document will be released on January 22.)

https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut4237ee

AP4 Coding Assistance Tool for RZ

AP4 for RZ V1.07.00 Release Note (This document will be released on January 22.)

https://www.renesas.com/search/keyword-search.html#genre=document&q=r20ut4216

2.1 Improvements to Functionality

The following improvements have been made.

(1) Support for multiple interrupts

If you are using IAR Embedded Workbench® for Arm® from IAR Systems, you can now enable multiple interrupts and generate multiple interrupt processing codes.

(2) Support for configuring Memory Protection Unit (MPU)

The MPU of Arm® Cortex®-R4 can now be configured. You can configure the MPU region size, attribute, and access permissions.

3. Updating Your Product

The method of updating depends on the product you are using.

Refer to the following for details. Update of either product is free of charge.

3.1 Updating the e² studio Code Generator Plug-in

For the method of updating e² studio, refer to section 3, "Updating Your Product" in RENESAS TOOL NEWS, Document No. R20TS0267EJ0100. This document will be released on January 22.

https://www.renesas.com/search/keyword-search.html#genre=document&g=r20ts0267

Note that you cannot update only the Code Generator plug-in.

3.2 Updating the AP4 Coding Assistance Tool for RZ

Download the installer from the URL below to install the program. The installer will be available from January 22. https://www.renesas.com/applilet_download

Revision History

		Description	
Rev.	Date	Page	Summary
1.00	Jan. 16, 2018	-	First edition issued
1.01	Aug. 17, 2020	1	(2) Support for configuring Memory Protection Unit (MPU): Description corrected

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061 Japan Renesas Electronics Corporation

■Inquiry

https://www.renesas.com/contact/

Renesas Electronics has used reasonable care in preparing the information included in this document, but Renesas Electronics does not warrant that such information is error free. Renesas Electronics assumes no liability whatsoever for any damages incurred by you resulting from errors in or omissions from the information included herein.

The past news contents have been based on information at the time of publication. Now changed or invalid information may be included.

The URLs in the Tool News also may be subject to change or become invalid without prior notice.

All trademarks and registered trademarks are the property of their respective owners.

© 2018 Renesas Electronics Corporation. All rights reserved.

TS Colophon 2.1